
Harris 1500 Return Instructions

General Conditions

- 1. No returns after 2:30 pm will be accepted.
- 2. The forms must be cleaned and free of excess concrete.
- 3. Panels must be returned on dunnage and banded. If you need safety strap kit for banding please notify your sales representative prior to your return.
- 4. Packaging of items is as follows.
 - Panels of Harris1500 should be returned in bundles as shown.
 - Accessories should be separated and placed in bags, pails, or crates. Use original packing whenever possible.
 - Taper Ties and She-Bolts must be separated and placed on skids to prevent damages during shipping. No nuts on Taper Ties or She-Bolts.


FAILURE TO FOLLOW RETURN SPECIFICATIONS WILL RESULT IN ADDITIONAL HANDLING CHARGES.


If you have any questions regarding how returns should be packaged or need to purchase safety strap kit, please contact your sales associate or our customer support department at (248-344-8260)



Pipe Braces


Separate into like sizes





Large Panels

- Separate into like sizes
- Band and set on dunnage
- Use 4 way chain loading sling to lift panels (max number: 5)



STD. Panels & Fillers

- Separate into like sizes
- Band and set on dunnage

FormTech

A White Cap Company

975 Ladd Rd. Walled Lake, Mi. 48390

I have received and understand return requirements

(Customer Signature)

(Date)